

TECHNICAL SERVICE BULLETIN



Triumph

December, 1975

SUBJECT:

HEATER AIR INTAKE APERATURE

MODELS:


TR7

In areas where heavy snowfalls are not uncommon, the possibility exists where snow and ice can become impacted in the heater intake causing a restriction and therefore possible failure of the blower motor.

A screen is available, Part No. HAC-105, which can be installed to the underside of the hood intake aperature, (refer to diagram).

Warranty claims will be accepted for this modification as follows:

Labor Allowance: 00.50 hrs.
Parts - 1 of Part No. HAC-105



J.P.