

TECHNICAL SERVICE BULLETIN

NO. 75-A-3

BRITISH



LEYLAND

Triumph

May, 1975

SUBJECT:

MODELS:

CHANGE OF SPARK PLUG

TR7

The spark plug specification for the TR7 has been changed from N11Y to N12Y.

Please ensure that all Service Personnel are aware of this specification change.

D.B.