

TECHNICAL SERVICE BULLETIN

NO. 76-B-3

Triumph

June, 1976

SUBJECT:

MODELS:

ELIMINATION OF CATALYST SERVICE
WARNING LIGHTTR7 & SPITFIRE
1975/76 MODELS ONLY**NOTE:-****THIS SERVICE BULLETIN APPLIES TO CALIFORNIA
CATALYST EQUIPPED VEHICLES ONLY** - - - - -

We are pleased to advise that the catalyst currently fitted to 1975 and 1976 Model Year Triumph Spitfire and TR7 has now been certified for a useful life of 50,000 miles.

As a result of this, it will no longer be necessary to replace the catalyst at 25,000 miles currently called for at the 25,000 mile service interval.

This certification is retroactive to the beginning of the 1975 Model Year, and all owners of record have been advised of this change. As a result of this new certification, the catalyst warning light is no longer required and therefore should be rendered inoperative.

METHOD OF WARNING LIGHT ELIMINATION - TR7

The catalyst warning indicator is the bottom light of the instrument panel warning light cluster. To render this light inoperative, simply remove the bulb.

TRIUMPH SPITFIRE

The catalyst warning indicator is easily accessible behind the center panel of the console. The warning light may be pushed out of the panel and the bulb removed.

Dealers are asked to perform this simple operation as a courtesy to their customers upon request.

A Sample Letter Mailed to Owners of Record Is
Printed On the Reverse Side of This Bulletin.

J.P.

TO ALL 1975/1976 MGB, MG MIDGET, TRIUMPH SPITFIRE & TR7 OWNERS

Dear Owner:

We are pleased to advise you that the Catalytic Convertor on your vehicle has now been certified for a useful life of 50,000 miles. At the time you purchased your car, the certification was for only 25,000 miles necessitating that the catalyst be replaced at that time. We have now been able to recertify your car so that this replacement will not be necessary until 50,000 miles.

All dealers have been advised of this change, and have been requested to render the Catalyst Warning Light inoperative upon your request. This minor modification will only take a few minutes to perform and will be carried out by your dealer upon presentation of this letter.

We are glad to have been able to save you time and expense through this recertification.

Yours Sincerely,

BRITISH LEYLAND MOTORS, INC.