

## TECHNICAL SERVICE BULLETIN

NO



# Triumph

October, 1976

SUBJECT:


BRAKE WARNING LIGHT RELAY

MODELS:

TR7

You may have noticed an additional relay which has been added to the TR7 (refer to diagram) on vehicles which have been arriving over the past few months, but which has not been depicted on the wiring diagram provided with the vehicle.

This relay, Lucas Part No. 33362, allows the driver to visually see that the brake warning lamp is functioning during the start mode (when starter motor is engaged).



J.P.