

TECHNICAL SERVICE BULLETIN

77-B-4

NO.



Triumph

June, 1977

SUBJECT:

SERVICING OF ELECTRONIC MODULES
FOR IN-BUILT ELECTRONIC DISTRIBUTORS

MODELS:

All

Listed below is the cross-reference information for electronic distributors, amplifiers and vacuum units fitted to 1977 models. This information is to be used in conjunction with the information and instructions contained in original bulletin #76-B-10.

<u>Vehicle</u>	<u>Dist.</u>	<u>Amplifier Vac. Assy.</u>	<u>Vacuum Unit</u>
Triumph Spitfire 1977 Federal	41697	54429790	54429788
Triumph Spitfire 1977 California	41698	54429455	54427198
Triumph TR7 1977 Federal	41701	83502	No vac unit
Triumph TR7 1977 California	41700	54429757	54429508

It should be noted that warranty replacement of the complete electronic distributor, due to an amplifier failure, is not acceptable unless amplifiers are unavailable through normal supply channels at the time of replacement.

JLNA

Provided Courtesy Triumph Wedg Owners Association
http://www.triumphwedgowners.org