



TECHNICAL SERVICE BULLETIN



TRIUMPH

December 1980
Date

ITEM T80/029

SUBJECT: 1980 MAINTENANCE SCHEDULES

MODELS: TR7; TR8

The 1980 TR8 carbureted specification Schedule A cards indicate the need to check and adjust the torque of the cylinder head nuts and bolts at the 1,000 mile service. This procedure is not required on the V8 engine.

The importance of cylinder head bolt torque checking on the TR7 is once again emphasized.

H.C.T.

Provided Courtesy Triumph Wedge Owners Association
<http://www.triumphwedgeowners.org>