



# TECHNICAL SERVICE BULLETIN



Date Jan/Feb '81

ITEM T81/01

SUBJECT: AXLE SHAFT CIRCLIP GROOVE

MODELS: TR7; TR8


New axle halfshafts incorporating a circlip groove have been introduced from VIN 204451.

The following part numbers are applicable:

<u>New Part Number</u>	<u>Description</u>	<u>Old Part Number</u>
RKC 4632	Axle Shaft Assy. R/H	TKC 2318
RKC 4633	Axle Shaft Assy. L/H	TKC 2319
GHK 1028	Bearing & Seal Kit	GHK 1019
ULC 2350	Collar, Axle Shaft	UKC 0414
ULC 2362	Circlip	-----

Bearing and seal kit, GHK 1019, can only be used on axle shafts without the circlip groove. Bearing and seal kit, GHK 1028 may be used with both types of halfshafts.

In the event that a halfshaft assembly is to be replaced on vehicles prior to the above VIN the modified parts should be fitted.



18/202