

# TECHNICAL SERVICE BULLETIN

NO. 75-F-5



# Triumph

October, 1975

SUBJECT:

WHEEL CYLINDER SEALS


MODELS:

ALL MODELS

The straight taper wheel cylinder seals, shown at 'A', are being superseded by chamfered lip seals, 'B'. These are shorter than those of the straight taper pattern. (Refer to diagram below).

This difference in length means that the seal occupies less of the groove in the piston.

The increased clearance that results is intentional and must not be taken to indicate an incorrect seal.



TB/70/4/75