

SERVICE & PARTS TECHNICAL INFORMATION

78-A-3



Triumph

SUBJECT:

Oil Filter GFE-147

MODELS:

Triumph TR-7

November 1978

Several reports have been received of the end seal gaskets being mounted off-center during the manufacturing steps on the GFE-147 oil filter supplied by British Leyland. This gasket, if not relocated, could cause the filter to not fit down fully on the engine adaptor pipe.

Please alert all concerned personnel to inspect the filter seals prior to installation and, if improperly installed, to gently peel the seal off the relocate so that it is centered over the filter endplate opening. The seals will readhere on a clean surface.