

ITEM T80/019

SUBJECT: FRONT SUSPENSION BLOCKS

MODELS: TR7, TR8

We take this opportunity to remind dealers that TR7 and TR8 vehicles utilize wood packing blocks in the front suspension to prevent possible damage during transportation.

These blocks must be removed as part of the pre-delivery inspection.

Please ensure that all service personnel are familiar with this procedure.

IMPORTANT: Vehicles must not be driven at more than 10 mph with the blocks in place.

H.C.T.